

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch

690 Walnut Ave.St. 150

Vallejo, CA 94592-1133

(707) 649-5453

(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 99.28**WELDING INSPECTION REPORT****Resident Engineer:**Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-015717**Date Inspected:** 16-Jul-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC) Chanxing Island **Location:** Shanghai, China**CWI Name:** Mr. Lv Li Qing**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG Segment**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance Inspector (QA), Vibin Kumar Selvanayaham, was present during the times noted above for observations relative to the work being performed.

Ultrasonic Testing (UT) – Document No: 006207

This QA inspector performed UT of approximately 10% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an UT report for this date. The members are identified as OBG Segment Bottom Plate. The weld designations reviewed are as follows:

1. BP3032-001-004, 005

Ultrasonic Testing (UT) – Document No: 006213 – UT After repair

This QA inspector performed UT of approximately 10% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an UT report for this date. The members are identified as OBG Segment 13AW bottom plate. The weld designations reviewed are as follows:

1. BP3033-001-001

Ultrasonic Testing (UT) – Document No: 006182 - Side 'A'

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

This QA inspector performed UT of approximately 10% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an UT report for this date. The members are identified as OBG Segment 13AW bottom plate. The weld designations reviewed are as follows:

1. BP3073-001-001, 002
2. BP3075-001-004, 005

Bay 16

This QA inspector observed ZPMC qualified welding personnel identified as 250050 perform Submerged Arc Welding (SAW) Welding on Longitudinal Diaphragm of OBG Segment 13AW, weld joint identified as LD3031-001-001. ZPMC QC is identified as Mr. Xia Chun Hui. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-B-T-2221-B-U3c-S-2.

This QA inspector observed ZPMC qualified welding personnel identified as 045265 perform SAW Welding on Longitudinal Diaphragm of OBG Segment 13AW, weld joint identified as LD3032-001-002. ZPMC QC is identified as Mr. Li Ming Yang. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-B-T-2221-B-U3c-S-2.

This QA inspector observed ZPMC qualified welding personnel identified as 045265 perform SAW Welding on Longitudinal Diaphragm of OBG Segment 13AW, weld joint identified as LD3036-001-001. ZPMC QC is identified as Mr. Li Ming Yang. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-B-T-2221-B-U3c-S-2.

This QA inspector observed ZPMC qualified welding personnel identified as 201583 perform Flux Cored Arc Welding (FCAW) Welding on Longitudinal Diaphragm of OBG Segment 13AW, weld joint identified as LD3036-001-001 and LD3032-001-002. ZPMC QC is identified as Mr. Li Ming Yang. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-B-T-2231-B-U2-F.

Visual Inspection after Blast

Segment 10AE

This QA Inspector performed a preliminary random visual inspection after the grit blast of the interior components of the deck panel, floor beams and corner assemblies of this segment. Areas of visual weld defects that will require welding were taped and will be repaired after the coating is applied. ZPMC QC personnel are aware of these areas and were present during the inspection.

Unless otherwise noted, all work observed on this date appeared to be in general compliance with the applicable contract documents.

Summary of Conversations:

Only general conversation was held between QA and QC concerning this project.

Comments

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact , who represents the Office of Structural Materials for your project.

Inspected By:	Kumar,Vibin	Quality Assurance Inspector
Reviewed By:	McClendon,Timothy	QA Reviewer
